

PRODUCT TROUBLESHOOTING

AC-0001-CSR

Date: 07/18/2006

Product: Window Air Conditioners

Applicable Models: HWR08XC6, HWR08XC6-T, HWR10XC6, HWR10XC6-T

Symptom: Side curtains provided with the unit doesn't extend to the desired length of 36 inches as described on the manufacturers' box.

Solution: Replacement curtains shown in (Fig. 1) can be ordered for customers. Part number for curtains is **AC-6100-39**. This should extend to 36 inches.




Fig. 1 AC-6100-39 Screen-Accordion