


Models: MC-7210, MC-7220




Models: MC-7210, MC-7220


- | | | |
|--|---|--|
| 1 P-000387 Screw, upper body | 11 ... P-000390 Hood Seal | 18 ... P-000397 Receptacle, power nozzle, 7220 |
| 2 P-000381 Cover | 12 ... P-000355 Connector Wire | 19 ... P-000048 Screw, motor mount |
| 3 P-000382 Dust Cover, 7210 | 13 ... P-000391 Strain Relief | 20 ... P-000398 Shield, motor |
| 3 P-000383 Dust Cover, 7220 | 14 ... P-000392 Power Cord Assembly | 21 ... P-000399 Screw, motor plate |
| 4 P-000384 Toggle Switch | 15 ... P-000393 Rear Wheel | 22 ... P-000400 Plate, motor mount |
| 5 P-000385 Motor Filter | 16 ... P-000394 Lower Body/Dust Compartment, 7210 | 23 ... P-000401 Motor Mount |
| 6 P-000386 Button, rocker switch | 16 ... P-000395 Lower Body/Dust Compartment, 7220 | 24 ... P-000402 Motor Assy |
| 7 P-000387 Screw, mount switch | 17 ... P-000396 Wheel Caster Assembly | 25 ... P-000403 Carbon Brush |
| 8 P- Mount Switch | | |
| 9 P-150PF Paper Bag, type C4, 5 pack | | |
| 10 ... P-000389 Bumper, extended | | |

Hose and Attachments

- P-000363 Hose Assembly, 7210
- P-000364 Hose Assembly, 7220
- P-000365 Handle Assy, 7210
- P-000366 Handle Assy, 7220
- P-000367 Spring, wand lock, 7220
- P-000368 Terminal Hose, (machine end coupling)
- P-000369 Hose Only, plastic
- P-000370 Lower Wand Assembly, plastic, 7210
- P-000371 Lower Wand Assembly, metal, 7220
- P-000372 Spring, wand lock, 7220
- P-000373 Dusting Brush, round
- P-000374 Upholstery Nozzle
- P-000375 Crevice Tool
- P-000376 Rug Nozzle, 7210
- P-000377 Brush, rug nozzle, 7210
- P-000378 Cord Straps, 7220
- P-000379 Cord & Plug Assembly, 7220




Agitator Assembly



- 1 P-000360 Pin & Dowel Assembly
- 2 P-000361 Bearing & Housing Assembly
- 3 P-0030 Washer

Models: MC-7220

Power Nozzle



- | | | | | |
|----|-------|----------|-------|------------------------|
| 1 | | P-000338 | | Floor Nozzle Upper |
| 2 | | P-000339 | | Bumper |
| 3 | | P-000340 | | Gasket |
| 4 | | P-000341 | | Onsert |
| 5 | | P-000342 | | Screw |
| 6 | | P-000343 | | Swivel Catch |
| 7 | | P-000344 | | Swivel Cap |
| 8 | | P-000345 | | Swivel |
| 9 | | P-000346 | | Swivel Bearing, seal |
| 10 | | P-000347 | | Motor Assy, complete |
| 11 | | P-000348 | | Motor Bracket |
| 12 | | P-000349 | | Gasket |
| 13 | | P-000350 | | Motor Seal |
| 14 | | P-000351 | | Seal, overload |
| 15 | | P-000352 | | Overload Protector |
| 16 | | P-000353 | | Motor Shaft Seal |
| 17 | | P-000354 | | Motor Seal |
| 18 | | P-000355 | | Connector Wire |
| 19 | | P-000356 | | Floor Nozzle Lower |
| 20 | | P-000357 | | Belt Guard |
| 21 | | P-000358 | | Screw |
| 22 | | P-270B | | Belt, CB4, 2 pk |
| 23 | | P-000507 | | Plug Socket |
| | | P-000359 | | Power Nozzle, complete |