

1

Items to Assemble:

- 6 Carriage Bolts
- 6 Wing Nuts

Place Bottom Shelf and Legs as shown.

After assembling tighten all Wing Nuts.

Qty: 6

Qty: 6

Left Side: (Use Upper Hole ONLY) to attach 1 Carriage Bolt and Wing Nut

Right Side: (Use both Upper and Lower Holes) 2 Carriage Bolts and Wing Nuts

2

Items to Assemble:

- 2 Wheel Assemblies
- 2 Leg Extenders
- 2 Hitch Pins

Hitch Pin - Qty: 2

Attach hitch pins to axle rod on wheel assembly after pushing through leg and shelf

3

Items to Assemble:

- 1 Grill Bottom with Control Panel
- 1 Heat Shield
- 2 Carriage Bolts
- 2 Wing Nuts
- 1 Condiment Basket
- 1 Wire Shelf

Qty: 2

Qty: 2

1st Place Wire Shelf in Third Hole From Top

4

Items to Assemble:

- 2 Shelves
- 8 Crown Nuts
- 8 Carriage Bolts

Qty: 8

Qty: 8

Repeat This Step for Left Sideshelf

5

Items to Assemble:

- 1 Vaporiser Bar
- 1 Grate

Grate Rests

Push Vaporiser Bar down onto rest in Grill Bottom

6

Items to Assemble:

- 1 Grill Lid
- 2 Hinge Pins
- 2 Hitch Pins

Qty: 2

Qty: 2

Hinge Pin and Hitch Pin

7

Item to Assemble:

- 2 Wing Nuts
- 1 Logo Plate
- 1 Handle
- 2 Screws
- 2 Washers
- 2 Spacers

Qty: 2

Qty: 2

8

Item to Assemble:

- 1 Warming Rack

1. Insert pivot wires into lid (A).

2. Flex leg wires to insert into holes in grill bottom (B).

(A) Pivot Wire

(B) Flex to insert

9

Items to Assemble:

- 1 Grease Clip
- 1 Tank Wire Support Bracket
- 1 LPD Gas Tank
- 1 Tank exclusion shelf

• Hang grease clip from center of grill bottom.

• Use an empty soup can (not included) to hang from grease clip.

**CAUTION**

• Failure to install can in clip will cause hot grease to drip from bottom of grill with risk of fire or property damage.

LP tank is sold separately. Fill and leak check tank before attaching to grill and regulator.

See Use and Care to perform the "Burner Flame Check" and important safety instructions before using.

**CAUTION**

Tank collar opening must face to front of cart once tank is attached.

Failure to install tank correctly may allow gas hose to be damaged in operation, resulting in the risk of fire.

Rear View of Grill

10

Correct position of LP tank and tank wire support bracket after grill assembly